MATERIAL SAFETY DATA SHEET

PRODUCT NAME: SPARTAN COTE PNW 15%

PRODUCT CODE: 02-0200

DATE REVISED

HMIS CODES: H F R P

2 3 Ø G

MANUFACTURER'S NAME: BURKE CHEMICALS

: 04-01-91

ADDRESS: 22039 S. Westward Av., Long Beach CA 90810

EMERGENCY PHONE: 1-800-424-9300

INFORMATION PHONE: (416) 665-7222

NAME OF PREPARER : PETER FUQUA

----- SECTION II - HAZARDOUS INGREDIENTS/SARA III INFORMATION -----

HAZARDOUS COMPONENTS	VAPOR PRESSURE Hg @ TEMP	
#AROMATIC HYDROCARBON (XYLENE) #1,2,4 TRIMETHYLBENZENE #CHMENE	21.0 190F N/A	79 4
#CUMENE	N/A	

[#] Indicates toxic chemical(s) subject to the reporting requirements of section 313 of Title III and of 48 CFR 372.

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT: 281 Deg F
VAPOR DENSITY: HEAVIER THAN AIR

SPECIFIC GRAVITY (H2D=1): 0.9
EVAPORATION RATE: SLOWER THAN ETHER

COATING V.O.C.: 6.16 LB/6L (739 G/L) MATERIAL V.O.C.: 6.16 LB/6L (739 G/L)

SOLUBILITY IN WATER: NON SOLUBLE

APPEARANCE AND ODOR: CLEAR LIQUID WITH SOLVENT ODOR

FLASH POINT: 70 Deg F METHOD USED: TCC FLAMMABLE LIMITS IN AIR BY VOLUME- LOWER: 1.0% UPPER: 7.0%

EXTINGUISHING MEDIA: FOAM, CO2, DRY CHEMICAL, WATER FOG

SPECIAL FIREFIGHTING PROCEDURES

REMOVE ALL ISNITION SOURCES. WEAR SELF CONTAINED BREATHING APPARATUS AND COMPLETE PERSONAL PROTECTIVE EQUIPMENT WHEN ENT-ERING CONFINED AREAS WHERE POTENTIAL EXPOSURE TO VAPORS OR PRODUCTS OF COMBUSTION EXISTS.

UNUSUAL FIRE AND EXPLOSION HAZARDS
CLOSED CONTAINERS WAY RUPTURE DUE TO BUILD UP OF PRESSURE WHEN EXPOSED TO HEAT.

SECTION V - REACTIVITY DATA ----

STABILITY: STABLE CONDITIONS TO AVOID HIGH HEAT

INCOMPATIBILITY (MATERIALS TO AVOID) AVOID CONTACT WITH STRONG OXIDIZING AGENTS, MINERAL ACIDS.

HAZARDOUS DECOMPOSITION OR BYPRODUCTS CARBON MONOXIDE, CARBON DIOXIDE, DXIDES OF NITROGEN.

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE HEADACHE AND DIZZINESS

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE SKIN: IRRITATION, SENSITIZATION AND DERMITITIS.

EYES: REDNESS, TEARING, IRRITATION.

SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE DERNITITIS, SENSITIZATION AND IRRITATION.

INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE CONVLISIONS AND LOSS OF CONSCIOUSNESS

HEALTH HAZARDS (ACUTE AND CHRONIC) ACUTE: HEADACH AND DIZZINESS

CHRONIC: UNKNOWN

CARCINOGENICITY: NTP? NO IARC MONOGRAPHS? NO OSHA REGULATED? YES

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE UNKNOWN

EMERGENCY AND FIRST AID PROCEDURES
INHALATION: REMOVE TO FRESH AIR. RESTORE BREATHING. TREAT SYMPTOMATICALLY.
EYES: FLUSH IMMEDIATELY WITH LARGE AMOUNTS OF WATER FOR 15 MINUTES, AND BET MEDICAL ATTENTION
SKIM: WASH WITH SOAP AND WATER. LAUNDER CLOTHING BEFORE RE-USE.
INGESTION: DO NOT INDUCE VOMITING. CONSULT A PHYSICIAN.

------ SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED SALVAGE FREE LIQUID WITH SHOVEL, BROADCAST ABSORBENT MATERIAL AND PLACE IN A SEALED CONTAINER.

WASTE DISPOSAL METHOD
DISPOSE OF HAZARDOUS WASTE IN ACCORDANCE WITH STATE, LOCAL AND FEDERAL RESULATIONS.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING PREVENT ALL EYE AND SKIN CONTACT. AVOID BREATHING VAPORS, STORE IN A COOL DRY PLACE WITH ADEQUATE VENTILATION.

OTHER PRECAUTIONS
KEEP DRUNS CLOSE TIENTLY AND IN AN UPRIGHT POSITION.

RESPIRATORY PROTECTION
NIOSH APPROVED RESPIRATOR PROTECTION IS REQUIRED.

VENTILATION
LOCAL AND MECHANICAL EXHAUST IS RECOMMENDED

PROTECTIVE GLOVES
NEOPRENE OR RUBBER

EYE PROTECTION SAFETY BOOKLES WITH SIDE SHIELD

OTHER PROTECTIVE CLOTHING OR EQUIPMENT FURTHER SAFETY EQUIPMENT NECESSARY TO PREVENT CONTACT WITH MATERIAL.

WORK/HYGIENIC PRACTICES WASH HANDS BEFORE HANDLING FOOD,

DISCLAIMER